

INSPECTION REPORT

Inspector's Name Blackwell, Michael		Inspector's Signature				Inspector's ID No. 11265	Report No. 97	Date yy mm dd 2022 08 26					
Railroad/Company Name & Address ALASKA RR CORP. 4923 N. Kipling Dr. Wasilla AK 99654					R/C R RR/Co. Code ARR	Division SYSTEM Subdivision SYSTEM	RR/Co. Representative (Receipt Acknowledged) Name Patrick Durand Title Email sewtrain557@gmail.com Signature _____						
From: City WASILLA	Codes 2790	Destination City & County				Codes	From Latitude						
State AK	02	City					From Longitude						
County MATANUSKA SUSITNA	C170	County					To Latitude						
Mile Post: From	To	Inspection Point ENGINE 557 WASILLA					To Longitude						
Activity Code:	230												
Units:	1												
Sub Units:	0												
Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
1	ARR	557	STM	230					WASILLA	N	N	0	230
Description - [** Comment to Railroad/Company **] Observed rebuild status of the 557 with Patrick Durand. Conducted internal boiler inspection prior to tube installation, left side throttle bracket assembly will need a lock not applied, no exceptions taken to the internal boiler inspection. Conducted inspection of internal fire box assembly prior to fire brick installation. All staybolts and firebox were newly manufactured, no exceptions taken.													
Seal Applied			Seal Removed			Hazard Class			UN/NA ID				
Violation Recommended				<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		Latitude:			Longitude:				
Written Notification to FRA of Remedial Action is:				<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional		Railroad Action Code		Date(mm/dd/yyyy):		Comments on back?			